


AD-A085 173


ACKENHEIL AND ASSOCIATES INC BALTIMORE MD F/G 13/13  
NATIONAL DAM INSPECTION PROGRAM. LAUREL HILL LAKE DAM (NDI I.D.--ETC(U)  
MAR 80 J D HAINLEY, T E DEBES DACW31-80-C-0026

UNCLASSIFIED

NL

1 OF 1  
ALL  
RIGHTS RESERVED





MICROCOPY RESOLUTION TEST CHART  
NATIONAL BUREAU OF STANDARDS-1963-A

ADA 085173

OHIO RIVER BASIN  
LAUREL HILL CREEK  
SOMERSET COUNTY

PENNSYLVANIA

NDI ID. NO. PA 267  
Penn. DER NO. 56-66

LEVEL

# LAUREL HILL LAKE DAM

COMMONWEALTH OF PENNSYLVANIA  
BUREAU OF STATE PARKS

## PHASE I INSPECTION REPORT


NATIONAL DAM INSPECTION PROGRAM.

*Laurel Hill Lake Dam (NDI ID. number PA-267, Penn. DER Number 56-66)*

*This River Basin,  
Laurel Hill Creek,  
Somerset County,  
Pennsylvania*

*Phase 1  
Inspection  
Report*

ORIGINAL CONTAINS COLOR PLATES: ALL DDB  
REPRODUCTIONS WILL BE IN BLACK AND WHITE



*10 James D. Hanley  
Timothy E. Debas*  
PREPARED FOR

DEPARTMENT OF THE ARMY  
BALTIMORE DISTRICT, CORPS OF ENGINEERS  
BALTIMORE, MARYLAND 21203

BY  
*Inc*  
ACKENHEIL & ASSOCIATES, BALTIMORE, MD, INC.  
7902 BELAIR ROAD  
BALTIMORE, MARYLAND 21236

*11* MARCH 1980

This document has been approved  
for public release and sale; its  
distribution is unlimited.

ACKENHEIL & ASSOCIATES

DACW31-80-C-0026

80 6 6 0 72

PREFACE

This report is prepared under guidance contained in the Recommended Guidelines for Safety Inspection of Dams, for Phase 1 investigations. Copies of these guidelines may be obtained from the Department of the Army, Office of Chief of Engineers, Washington, D.C. 20314.

The purpose of a Phase 1 investigation is to identify expeditiously those dams which may pose hazards to human life or property. The assessment of the general condition of the dam is based upon visual observations and review of available data. Detailed investigation and analyses involving topographic mapping, subsurface investigations, material testing, and detailed computational evaluations are beyond the scope of a Phase 1 investigation; however, the inspection is intended to identify any need for such studies which should be performed by the owner.

In reviewing this report, it should be realized that the reported condition of the dam is based on observations of field conditions at the time of inspection along with data available to the inspection team. In cases where the reservoir was lowered or drained prior to inspection, such action, while improving the stability of the dam, removes the normal load on the structure and may obscure certain conditions which might otherwise be detectable if inspected under the normal operating environment of the structure.

It is important to note that the condition of the dam depends on numerous and constantly changing internal and external factors which are evolutionary in nature. It would be incorrect to assume that the present condition of the dam will continue to represent the condition of the dam at some point in the future. Only through frequent inspections can unsafe conditions be detected and only through continued care and maintenance can these conditions be prevented or corrected.

Phase 1 inspections are not intended to provide detailed hydrologic and hydraulic analyses. In accordance with the established Guidelines, the spillway design flood is based on the estimated "Probable Maximum Flood" (PMF) for the region (greatest reasonably possible storm runoff), or fractions thereof. The spillway design flood provides a measure of relative spillway capacity and serves as an aid in determining the need for more detailed hydrologic and hydraulic studies, considering the size of the dam, its general condition, and the downstream damage potential.

PHASE 1 INSPECTION REPORT  
NATIONAL DAM INSPECTION PROGRAM

SYNOPSIS OF ASSESSMENT AND RECOMMENDATIONS

NAME OF DAM:	Laurel Hill Lake Dam
STATE LOCATION:	Pennsylvania
COUNTY LOCATION:	Somerset
STREAM:	Laurel Hill Creek, a tributary of the Casselman River
DATES OF INSPECTIONS:	November 20, 1980, and March 4, 1980
COORDINATES:	Lat. 39° 59.4', Long. 79° 14.5'

ASSESSMENT

Laurel Hill Lake Dam is classified as an "intermediate" size, "high" hazard dam in accordance with U. S. Army Corps of Engineers dam safety criteria.

Based on the evaluation of available design information and visual observations of conditions as they existed on the dates of the field reconnaissances, the general condition of Laurel Hill Lake Dam is considered to be good. However, the cause and origin of a seepage zone located downstream of the dam embankment could not be conclusively established by visual observation and review of the construction drawings. Therefore, it is recommended that periodic monitoring of the seep be made by the dam owner. The presence of eroded footpaths, animal burrows, cracking and spalling on concrete surfaces, and shallow depression located on the dam crest, are considered minor deficiencies in need of maintenance.

Guideline criteria recommend a PMF spillway design flood for "intermediate" size, "high" hazard dams. Spillway discharge capacity was found to be seriously inadequate based on the following data:

- (1) Maximum non-overtopping spillway discharge capacity is 34 percent PMF,
- (2) Failure of the dam resulting from 37 percent PMF overtopping significantly increases the downstream loss of life and damage potential compared to that which would exist prior to dam failure.

Laurel Hill Lake Dam is categorized as "unsafe, non-emergency" in accordance with recommended criteria.

RECOMMENDATIONS

The following recommendations should be implemented as soon as possible:


1. Implement additional studies by a professional engineer experienced in the design of dams to more accurately ascertain spillway channel adequacy and the extent of improvements required to provide sufficient discharge capacity or erosion/breaching protection for the dam.

RECOMMENDATIONS (cont.)

Laurel Hill Lake Dam  
NDI ID. NO. PA 267

Improvements found necessary by the recommended study should be implemented immediately.

2. Monitor seepage and adjoining wet zone located at the downstream embankment toe. If increased flow quantity or evidence of erosion is observed, the Department of Environmental Resources, Dam Safety Division should be notified immediately, and necessary corrective repairs made.
3. Develop a formal flood surveillance and warning plan.
4. Backfill, mulch, and seed slope erosion, animal burrows, and shallow depression located on embankment slopes and crest.
5. Repair, when necessary, spalled and cracked concrete surfaces on spillway channel sidewalls and reservoir drain control structure.



*James D. Hainley* 4/11/80  
James D. Hainley, P.E. Date  
A Registration No. 9453  
Vice President

*Timothy E. Debes* 4/11/80  
Timothy E. Debes Date  
Project Manager

*John G. Schultz* 11 APR 80  
John G. Schultz Date  
Project Engineer

APPROVED BY:

*James W. Peck* 9 May 1980  
JAMES W. PECK Date  
Colonel, Corps of Engineers  
District Engineer

Accession For	
NTIS	<input checked="" type="checkbox"/>
DDC TAB	<input type="checkbox"/>
Unannounced	<input type="checkbox"/>
Justification	<input type="checkbox"/>
By	<i>a file</i>
Distribution	
Availability Codes	
Dist	Available for special
A	

LAUREL HILL LAKE DAM



OVERVIEW OF DAM

## TABLE OF CONTENTS

	<u>Page</u>
PREFACE . . . . .	i
SYNOPSIS OF ASSESSMENT AND RECOMMENDATIONS . . . . .	ii
OVERVIEW PHOTOGRAPH . . . . .	iv
SECTION 1 - PROJECT INFORMATION	
1.1 General . . . . .	1
1.2 Description of Project . . . . .	1
1.3 Pertinent Data . . . . .	3
SECTION 2 - ENGINEERING DATA	
2.1 Design . . . . .	5
2.2 Construction . . . . .	6
2.3 Operation . . . . .	6
2.4 Evaluation . . . . .	7
SECTION 3 - VISUAL INSPECTION	
3.1 Findings . . . . .	8
3.2 Evaluation . . . . .	10
SECTION 4 - OPERATIONAL FEATURES	
4.1 Procedure . . . . .	11
4.2 Maintenance of Dam . . . . .	11
4.3 Inspection of Dam . . . . .	11
4.4 Maintenance of Operating Facilities . . . . .	11
4.5 Warning System . . . . .	11
4.6 Evaluation . . . . .	11
SECTION 5 - HYDROLOGY AND HYDRAULICS	
5.1 Evaluation of Features . . . . .	12
SECTION 6 - STRUCTURAL STABILITY	
6.1 Evaluation of Structural Stability . . . . .	15



## TABLE OF CONTENTS (cont'd)

	<u>Page</u>
<b>SECTION 7 - ASSESSMENT AND RECOMMENDATIONS</b>	
7.1 Dam Assessment . . . . .	17
7.2 Recommendations . . . . .	18
<b>APPENDIX A - VISUAL OBSERVATIONS CHECK LIST AND FIELD SKETCH</b>	
Visual Observations Check List . . . . .	A1
Field Sketch . . . . .	A10
Field Profile and Section . . . . .	A11
<b>APPENDIX B - ENGINEERING DATA CHECK LIST</b> . . . . .	B1
<b>APPENDIX C - PHOTOGRAPHS</b>	
Photograph Key Map . . . . .	C1
Photographs 1 through 8 . . . . .	C2
<b>APPENDIX D - HYDROLOGIC AND HYDRAULIC ENGINEERING AND COMPUTER DATA</b>	
Hydrologic and Hydraulic Engineering Data . . . .	D1
HEC-1 Dam Safety Version	
Data Base . . . . .	D2
Storage vs. Elevation . . . . .	D3
Computer Input - Overtopping Analysis . . . . .	D4
Computer Output - Summary of Overtopping Analysis . . . . .	D5
Computer Input - Breach Condition . . . . .	D6
Computer Output - Summary Breach Condition . . . .	D8
Summary of Flood Stages for 37 Percent PMF . . . .	D11
<b>APPENDIX E - LOCATION PLAN AND PLATES</b>	
Location Plan . . . . .	E1
Plates 1 through 5 . . . . .	E2
<b>APPENDIX F - REGIONAL GEOLOGY</b>	
Regional Geology . . . . .	F1
Geologic Map . . . . .	F2

PHASE 1 REPORT  
NATIONAL DAM INSPECTION PROGRAM  
LAUREL HILL LAKE DAM  
NDI ID. NO. PA 267

SECTION 1  
PROJECT INFORMATION

1.1 GENERAL

- A. AUTHORITY: This study was performed pursuant to the authority granted by the National Dam Inspection Act, Public Law 92-367, to the Secretary of the Army, through the Corps of Engineers, to conduct inspections of dams throughout the United States.
- B. PURPOSE: The purpose of this study is to determine if the dam constitutes a hazard to human life or property.

1.2 DESCRIPTION OF PROJECT

A. DAM AND APPURTENANCES

1. Embankment: Laurel Hill Lake Dam was constructed as a zoned earthfill structure. The dam embankment is approximately 700 ft. long, has a maximum toe to crest height of 32 ft., and a crest width of 13 ft. The upstream embankment slopes are 3H:1V from dam crest to top of riprap layer (El. 1943.5) and 2.5H:1V from El. 1943.5 to embankment toe. The downstream slope has an inclination of 2H:1V.

2. Seepage Control Provisions: A cutoff trench is located at dam centerline and extends the full length of the dam and spillway channel. The cutoff trench was constructed of impervious clay and extends about 10 ft. below the dam foundation. (Refer to Plate No. 5.)

The downstream embankment toe was constructed with gravel and has been modified to include a rock and gravel filter drain at the location of the original Laurel Hill Creek stream channel (100 ft. north of the spillway channel). A 6 in. dia. tile drain has been installed in this section of the embankment toe to drain seepage collected by the filter. (Refer to Plate No. 1.)

3. Flood Discharge Facilities: Flood discharge facilities consist of an ungated, 115 ft. wide spillway channel and a 4 x 4 ft. reservoir drain culvert controlled by a slide gate.

The spillway channel is located at the left dam abutment and consists of an ogee crest, a 30.5 ft. long channel, and a 52 ft. long concrete stilling basin. (Refer to Plate Nos. 1 and 5.)

According to construction drawings, a 4 x 6 ft. orifice is formed in the right spillway channel sidewall, 2 ft. upstream from the spillway ogee crest, and is protected by a trash rack. (Refer to Plate No. 2.) The 4 x 4 ft. concrete culvert extends 110 ft. to a concrete head wall, located about 30 ft. downstream from the end wall of the spillway channel stilling basin.

- B. LOCATION: Laurel Hill Lake Dam is located in Laurel Hill State Park, Somerset County, Pennsylvania, less than one mile north of Trent and 4.3 miles northwest of New Centerville. The dam is situated on Laurel Hill Creek, a southward flowing tributary of the Casselman River. (Refer to Location Plan, Appendix E.)
- C. SIZE CLASSIFICATION: The dam has a maximum top of dam storage capacity of 1,330 ac.-ft. and a toe to crest height of 32 ft. Based on maximum storage capacity, the dam is classified as an "intermediate" size structure.
- D. HAZARD CLASSIFICATION: Laurel Hill Lake Dam is classified as a "high" hazard structure. In the event of dam failure approximately thirty (30) inhabited residences located within a 5.5 mile downstream channel reach would be subject to substantial damage and loss of life.
- Additional property damage would be expected to occur to township roads, bridges, and a waste water treatment facility.
- E. OWNERSHIP: Laurel Hill Lake Dam is owned by the Commonwealth of Pennsylvania, and as a State Park facility, its operation and maintenance are the responsibility of the Bureau of State Parks. All correspondence concerning maintenance and operation procedures should be directed to Resources Management Bureau, Department of Environmental Resources, P. O. Box 1467, Harrisburg, Pennsylvania 17120.
- F. PURPOSE OF DAM: The dam was constructed for use as a recreational facility.
- G. DESIGN AND CONSTRUCTION HISTORY: The dam was designed by the Branch of Recreational Planning and State Cooperation of the National Park Service (Department of the Interior) in 1937. Construction of the dam was completed in 1940.

A rehabilitation project, designed by the Pennsylvania Department of Forests and Waters in 1963 included construction of grouted stone gutters along the spillway channel sidewalls and a tile drain embedded in a rock and gravel filter, extending 100 ft. through the downstream embankment toe near the right spillway sidewall. (Refer to Plate No. 1.) Further modifications included repairing the concrete surfaces of the spillway sidewalls and reservoir drain control structure, replacing the slide gate lift mechanism, and restoring the dam crest surface. (Refer to Plate Nos. 2, 3, and 4.)

- H. NORMAL OPERATING PROCEDURES: Laurel Hill Lake Dam normally operates as an uncontrolled structure with the reservoir drain slide gate closed. Pool elevation is maintained at El. 1938.5 by the ogee crest of the spillway channel.

1.3 PERTINENT DATA

A. DRAINAGE AREA 43.65 sq. mi.

B. DISCHARGE AT DAM FACILITY

Maximum discharge at dam facility Unknown  
Maximum ungated spillway channel capacity 16,600 cfs

C. ELEVATION (FT. ABOVE MSL)

Constructed top of dam 1950.0 ft.  
Spillway channel crest 1938.5 ft.  
Normal pool 1938.5 ft.  
Maximum tailwater Unknown  
Invert of reservoir drain inlet 1915.0+ ft.  
Invert of reservoir drain outlet 1913.0+ ft.  
Streambed at dam centerline 1918.0+ ft.

D. RESERVOIR LENGTH

Length of maximum pool 1.3 mi.  
Length of normal pool 1.0 mi.

E. STORAGE CAPACITY

Constructed top of dam 1330 ac.-ft.  
Spillway channel crest 395 ac.-ft.  
Normal pool level 395 ac.-ft.

F. RESERVOIR SURFACE AREA

Constructed top of dam 84 acres  
Spillway crest 58 acres  
Normal pool 58 acres  
Sediment pool Unknown

G. DAM EMBANKMENT

Type Zoned Earthfill  
Length 700 ft.  
Height 32 ft.  
Crest width 13 ft.  
Side slopes  
Downstream 2H:1V  
Upstream  
From toe to El. 1943.5 2.5H:1V  
From El. 1943.5 to crest 3H:1V

G. DAM EMBANKMENT (Cont.)

Impervious core	Yes
Core cutoff trench	Yes
Grout curtain	None

H. SPILLWAY CHANNEL

Type	Ogee crest
Cross section	Rectangular
Width	115.0 ft.
Crest elevation	1938.5 ft.
Gate	None
Length of channel	30.5 ft.
Sidewall height above crest	12.0 ft.

I. RESERVOIR DRAIN

Type	4 x 4 ft. concrete culvert
Orifice	6 x 4 ft.
Outlet	5.5 x 4 ft.
Culvert length	110 ft.
Slope	2 percent
Gates	4 x 4 ft. slide gate stop log gate

J. STILLING BASIN

Type	Plunge pool
Apron	Concrete
Chute blocks	None
Baffle blocks	None
End sill	None
End cutoff wall	Yes
Length	52 ft.
Width	115 ft.
Depth of pool	4 ft.

## SECTION 2 ENGINEERING DATA

### 2.1 DESIGN

A. DATA AVAILABLE: The following available data was obtained from the Pennsylvania Department of Environmental Resources, Dam Safety Division, Harrisburg, Pennsylvania.

1. Hydrology and Hydraulics: No design reports specific to Laurel Hill Lake Dam were available.
2. Dam and Appurtenances: The available data consists of one (1) design drawing prepared by the Branch of Recreational Planning and State Cooperation of the National Park Service (U. S. Department of the Interior) dated February 26, 1937, and four (4) preliminary design drawings prepared by the Pennsylvania Department of Forests and Waters. The National Park Service drawing shows the crest profile, sections of the embankment, spillway channel and side-walls, and a proposed design change in riprap placement. The Department of Forests and Waters drawings include a site plan, section views of spillway sidewalls and the reservoir drain control structure, and details of appurtenances.

B. DESIGN FEATURES: Illustrations of principal design features are shown on Plate Nos. 1 through 5.

1. Embankment: According to the original design drawings, the zoned earthfill embankment rests on successive layers of sandy clay, clay, and shale above sandstone bedrock. Riprap on the upstream slope, placed between El. 1943.5 and El. 1933.5 is reportedly supported above the lake bottom by a compacted layer of gravel and clay. The hand-placed riprap provides protection to the embankment from erosion by wave action.

The embankment clay core, located at the dam centerline tapers on a 1H:4V slope to an 8 ft. width at the dam crest.

2. Seepage Control Provisions: According to construction drawings, a cutoff trench was constructed as a continuation of the embankment core. The cutoff trench has a bottom width of 8 ft., 1H:2V side slopes, and extends to sandstone bedrock.

Seepage control provisions also include a gravel and rock filter drain installed in the downstream embankment toe. This toe drain extends about 100 ft. from the right spillway

channel sidewall towards the right abutment. The drain consists of an 18 in. thick blanket of gravel supporting an 18 in. thick blanket of rock. A 6 in. tile drain pipe was installed in the toe of the filter drain to collect seepage and divert it to an open drainage ditch, located 35 ft. downstream of the dam embankment. Flow from the drainage ditch enters Laurel Hill Creek about 55 ft. downstream of the dam.

3. Flood Discharge Facilities: Details of the spillway channel and the reservoir drain culvert are shown on Plate Nos. 1 through 5.

The spillway channel consists of an ogee crest, open channel, and stilling basin. Concrete sidewalls are 12 ft. high at the ogee crest. The rectangular stilling basin has a 52 ft. long reinforced concrete apron. The downstream end of the apron is sloped upward to maintain a 4 ft. deep pool in the stilling basin. Stone riprap has been hand-placed on both sides of the exit stream channel, and extends 30 ft. downstream. (Refer to Plate No. 1.)

The invert of the reservoir drain inlet is El. 1915, approximately 1 ft. above lake bottom and 23.5 ft. below the lake surface during normal pool conditions. A stop log gate, slide gate, and manual lift mechanism are housed in a concrete control structure, located on the dam crest, at the embankment side of the right spillway sidewall. The stop log gate can be lowered to obstruct culvert flow and permit dewatering of the control structure for maintenance purposes. Access to the slide gate and lift mechanism is provided by an 8 ft. square opening with a steel grate cover located on top of the control structure.

Flow from the reservoir drain exits at a concrete head wall located about 30 ft. downstream from the end wall of the stilling basin. The 5.5 x 4 ft. outlet is submerged and the flow is discharged directly into Laurel Hill Creek.

- 2.2 CONSTRUCTION: Field observations indicate that the dam was constructed in general accordance with available construction drawings. There is no record of any additional modifications made to the dam after renovations were made in 1964.
- 2.3 OPERATION: The Commonwealth of Pennsylvania, Bureau of State Parks, is responsible for the operation of Laurel Hill Lake Dam. The dam is generally operated as an uncontrolled structure and no performance records are maintained. The only operational feature is a manually operated slide gate reportedly inspected annually. This slide gate was not operated during the field reconnaissances.

## 2.4 EVALUATION

- A. AVAILABILITY: All available construction information and drawings were provided by the Pennsylvania Department of Environmental Resources, Dam Safety Division, Harrisburg, Pennsylvania.
- B. ADEQUACY: The construction drawings and design data provided are reasonably documented and are considered adequate to evaluate the dam and appurtenant structures in accordance with the scope of a Phase 1 study. Based on the review of this data, the dam and appurtenant structures are considered to have been designed in general conformance with accepted engineering practice.
- C. VALIDITY: At this time, there is no observable evidence or reason to question the validity of the available construction information and drawings.



### SECTION 3 VISUAL INSPECTION

#### 3.1 FINDINGS

A. GENERAL: The on-site reconnaissance of Laurel Hill Lake Dam consisted of:

1. Visual observations of the earth embankment, abutments, and spillway channel.
2. Visual observations of exposed sections of the reservoir drain culvert, slide gate control structure, reservoir, and downstream channel.
3. Visual observations of discernible hazardous conditions or safety deficiencies.
4. Evaluation of the downstream hazard potential.
5. Transit stadia survey of relative elevations along the embankment crest centerline, spillway, and across the embankment slopes.

Visual surveys were performed during periods when reservoir and tailwater were at normal pool levels.

A visual observation check list and field sketch are given in Appendix A. Specific observations are illustrated in photographs of Appendix C.

B. EMBANKMENT

1. Embankment Surface: Upstream embankment slope has a dense grass covering and hand-placed rock riprap extending from normal pool level to about El. 1943.5. An eroded footpath is located about 160 ft. south of the right abutment and extends from normal pool level to dam crest and down the downstream embankment slope. Animal burrows were found on both embankment slopes at locations shown on the field sketch in Appendix A. A shallow depression is located in front of the reservoir drain control structure on the dam crest. The downstream embankment slope has a dense grass covering and a Department of Forest and Water boundary marker located at about mid-slope approximately 100 ft. north of the spillway channel. Field survey measurements indicate the downstream embankment slope is inclined 2H:1V, whereas the upstream embankment slope is inclined 3H:1V from dam crest to top of riprap layer (El. 1943.5), and 2.5H:1V from top of riprap to normal pool level. A gravel access road, frequently used during the summer months, is located at the right upstream embankment-abutment junction.

2. Seepage Zone: A seep and an adjoining wet zone were observed located about 45 ft. below the downstream embankment toe and about 200 ft. north of the spillway-stilling basin. The seep was observed to discharge clear water at an estimated flow rate of 8 gpm. Reportedly the seep and wet zone have existed for several years and are believed the result of spring activity.

The seep and adjoining wet zone are located in a topographic low near the location of the old stream channel, and drain in a direction towards Laurel Hill Creek.

C. APPURTENANT STRUCTURES

1. Spillway Channel: Spillway channel crest, bottom, and side-walls are of concrete construction and appear structurally sound. However, minor evidence of spalling and cracking was observed on exposed sections of the spillway channel sidewalls. Also, an eroded footpath extends along the upstream spillway-abutment junction sidewall. Concrete gutters are located along both downstream sidewalls of the spillway channel.

Spillway channel inlet, outlet, and stilling basin were found free of significant debris and flow obstructions.

2. Outlet Works: Exposed sections of the reinforced concrete reservoir drain control structure appeared in good condition. However, some evidence of spalling and cracking was apparent on exterior concrete surfaces.

Reservoir drain culvert inlet and outlet were submerged and could not be observed.

Reservoir drain slide gate and lifting mechanisms were not operated during the field reconnaissances. However, the slide gate and lifting mechanisms are reportedly operational.

- D. RESERVOIR AREA: No evidence of significant slope instability or shoreline erosion was observed during the field reconnaissances. Reservoir slopes have gentle to moderate inclinations and are predominately covered with trees and thick vegetation. Sediment from reservoir side slopes and beach areas are occasionally washed into the reservoir during heavy surface runoff.
- E. DOWNSTREAM CHANNEL: The spillway channel stilling basin discharges into an outlet channel approximately 100 ft. in width. Outlet channel bottom is cobble lined, with side slopes covered by grass and tree growth. The downstream channel appeared stable and was found free of debris and flow obstructions. Approximately thirty (30) inhabited structures are located within an estimated 15 ft. elevation difference of Laurel Hill Creek within a 5.5 mile channel reach between the dam and Barronvale, Pennsylvania.

### 3.2 EVALUATION

#### A. EMBANKMENT

1. Embankment Surface: In general, the dam embankment is adequately maintained and appears in good condition. The eroded footpath, animal burrows, and shallow depression observed on embankment slopes and crest are surficial deficiencies and are not considered to represent significant hazard to the dam. However, remedial repairs should be made as soon as possible.
2. Seepage Zone: Although believed attributable to spring activity, the cause and origin of the observed seepage could not be conclusively established by visual observation and review of construction documents. It is therefore recommended the seep and adjoining wet zone be periodically monitored by the dam owner to note any change in conditions. If an increase in flow quantity or evidence of erosion is observed, the Department of Environmental Resources, Dam Safety Division should be notified immediately and necessary corrective repairs made.

- B. APPURTENANT STRUCTURES: The spillway channel and stilling basin appear to be functioning as designed and are considered to be in good condition. Spalling and cracking of channel side-wall and control structure surfaces should be visually observed on a periodic basis and corrective repairs made as necessary.

SECTION 4  
OPERATIONAL FEATURES

- 4.1 PROCEDURE: Reservoir level is normally maintained at El. 1938.5 by passage of base flow over the ogee crest of the spillway channel. Since the dam routinely operates as an uncontrolled structure, a dam tender is not required. The only control features of the dam are a slide gate and stop log gate which are used to regulate the reservoir drain culvert. The slide gate is infrequently operated and is normally closed. The gate can be inspected at normal pool by lowering the stop log gate and dewatering the control structure.
- 4.2 MAINTENANCE OF DAM: The dam embankment and appurtenant structures are maintained by the Pennsylvania Bureau of State Parks. Normal maintenance usually includes mowing the embankment slopes, applying seed and fertilizer, and servicing the reservoir drain gates and lift mechanisms. Maintenance is reportedly performed on an "as-needed" basis.
- 4.3 INSPECTION OF DAM: Inspections of Laurel Hill Lake Dam are conducted annually by the Pennsylvania Bureau of State Parks and biennially by the National Park Service. Inspections generally consist of visual observations of the embankment and appurtenant structures and providing repair recommendations.
- 4.4 MAINTENANCE OF OPERATING FACILITIES: The reservoir drain slide gate and stop log gate are the only operational features of the dam. The reservoir drain gates are normally inspected and operated annually by State Park personnel. Both gates were found closed and were not operated during field reconnaissances made prior to this report. However, the gates are reported to be operable and in good condition.
- 4.5 WARNING SYSTEM: The Park Superintendent reportedly monitors the dam facility during periods of unusually heavy rainfall and alerts Civil Defense authorities as required. However, no formal flood warning plan is in effect.
- 4.6 EVALUATION: With the exception of no formally instituted flood warning plan, the current operational and maintenance procedures at Laurel Hill Lake Dam are considered to be adequate. A formal flood warning and evacuation plan is needed for the protection of park users and downstream residents.

SECTION 5  
HYDROLOGY/HYDRAULICS

5.1 EVALUATION OF FEATURES

- A. DESIGN DATA: The watershed of Laurel Hill Lake Dam has an area of approximately 28,000 acres and ranges in topographic relief from normal pool El. 1938.5 to El. 2980. Watershed cover complex is approximately 60 percent forest and 40 percent open pasture and farmland. Among the lakes and ponds located upstream from Laurel Hill Lake Dam are three ski area "snow making" ponds, two fish hatchery networks, Laurelridge Lake, Kooser Lake, the Bakersville Reservoir, and two unnamed lakes south of Pennsylvania Route 31 near Jimtown. These identified bodies of water are not considered to have a significant effect on the safety or performance of the dam.

At normal pool, Laurel Hill Lake Dam impounds a reservoir with a surface area of 58 acres and a storage volume of about 395 ac.-ft. Top of dam storage capacity is approximately 1,330 ac.-ft.

- B. EXPERIENCE DATA: Records are not kept of reservoir stage elevations or rainfall amounts. There is no report of the dam embankment ever having been overtopped.

As previously stated, Laurel Hill Lake Dam is classified as an "intermediate" size, "high" hazard dam. According to guidelines established by the U. S. Army Corps of Engineers, the required spillway design flood (SDF) for this dam facility is the Probable Maximum Flood (PMF).

The PMF inflow hydrograph for Laurel Hill Lake was modeled using the HEC-1 Dam Safety Version computer program. This hydrograph was routed through the reservoir and dam spillway and produced a calculated PMF peak outflow rate of 50,500 cfs. Computer input data and summary of output are presented in Appendix D.

- C. VISUAL OBSERVATIONS: No serious deficiencies or other adverse conditions were observed during the field reconnaissances that would significantly reduce spillway discharge capacity or prevent the channel from functioning as designed.
- D. OVERTOPPING POTENTIAL: Various percentages of PMF were routed through the reservoir to estimate the percent PMF outflow that the spillway can adequately pass without overtopping the dam. Computer analyses indicate that the spillway channel can hydraulically pass a maximum of about 34 percent of the PMF without overtopping the dam. The analyses also indicate that Laurel Hill Lake Dam is overtopped for a period of 6 hours with a maximum depth of 2.44 ft. for 50 percent PMF conditions. PMF runoff overtops the dam for 13.5 hours and produces an estimated maximum overflow depth of 6.2 ft.

#### E. ADEQUACY OF SPILLWAY CHANNEL

1. General: Spillway adequacy was evaluated in accordance with procedures and guidelines established by the U. S. Army Corps of Engineers for Phase 1 hydrologic and hydraulic studies.

As previously indicated by the overtopping potential analysis, the spillway channel does not have adequate capacity to pass the recommended spillway design flood of 100 percent PMF without overtopping the dam. Guideline criteria requires that an estimate of the likelihood of dam failure and an assessment of downstream damage and loss of life consequences be made for dams overtopped by less than 50 percent PMF conditions.

The HEC-1 Dam Safety Version computer program was used to evaluate breaching of the dam and to estimate the downstream hydrologic/hydraulic consequences of assumed structural failures caused by overtopping. This data was used to assess the adequacy of the spillway channel.

2. Method of Analysis: A breach analysis was conducted to estimate if dam failure resulting from overtopping would significantly increase loss of life or property damage downstream from the dam compared to what would exist just before dam failure. This analysis was performed in three steps:
  - a. Step 1: A failure storm of 37 percent PMF was selected to initiate breaching of the dam.
  - b. Step 2: The selected 37 percent PMF hydrograph was routed through Laurel Hill Lake and downstream damage centers to provide an estimate of flood stages prior to incipient failure of the dam. These flood stages served as a reference level of damage and were compared to those produced during the breach analysis.
  - c. Step 3: Breach flood stages at the designated damage centers were estimated by routing the 37 percent PMF inflow hydrograph combined with the discharge contributed by failure of the dam. The breach analysis was based on the following data:

1) Depth of overtopping flow at onset of failure	0.75 ft.
2) Breach bottom width	70 ft.
3) Maximum breach top width	85 ft.
4) Maximum breach height	30 ft.
5) Duration of failure	0.5 hrs.

3. Results: Computer analyses indicate downstream flood stages would be raised by between 4.1 and 6.3 ft. by the assumed dam breach (refer to Summary of Flood Stages for 37 Percent PMF, D-11 in Appendix D).

Field reconnaissance and map review indicate that dam failure, according to the selected breach model, will increase flood stages enough to inundate two (2) residences in the vicinity of Sta. 1 and one (1) residence at Sta. 2. Furthermore, seven (7) residences located downstream from Sta. 4 are expected to experience a significant increase in loss of life and damage potential for dam breach conditions. (Refer to Location Plan in Appendix E for damage center station locations.)

Based on the above data, breach flood flows are considered to significantly increase the loss of life and the downstream damage potential. Accordingly, spillway channel discharge capacity is assessed to be seriously inadequate.

SECTION 6  
STRUCTURAL STABILITY

6.1 EVALUATION OF STRUCTURAL STABILITY

A. VISUAL OBSERVATIONS

1. Embankment: Surficial embankment deficiencies identified in Section 3.1-B1 are not considered to have a significant effect on dam stability. However, the observed seepage and adjoining wet zone located about 45 ft. from the downstream embankment toe and about 200 ft. north of the spillway channel (refer to Field Sketch, Appendix A) are considered to represent a potential hazard to the dam. The cause and origin of the seepage could not be conclusively determined by visual observation and review of construction drawings. However, the seep and wet zones, in their present condition, are not considered to represent a significant hazard to the dam at this time. Periodic monitoring of the zones by the dam owner is recommended.
2. Appurtenant Structures: Except for some evidence of minor concrete spalling, no significant evidence of structural distress was observed during the field reconnaissances that would significantly affect hydraulic performance or the stability of the dam.

B. DESIGN AND CONSTRUCTION DATA

1. Subsurface Exploration: No subsurface exploration reports were available. According to the original design drawing (Plate No. 5), the embankment cutoff trench was excavated through layers of sand clay, clay, and shale to sandstone bedrock.
2. Laboratory Testing: No laboratory test reports were available, nor was any reference made to laboratory testing in the available information.
3. Slope Stability Analysis: No calculations or references to slope stability analyses were found in available source material. Based upon embankment geometry, visual observations, and performance history, the static slope stability of the embankment is presumed adequate.
4. Seepage Analysis: No calculations or references to seepage analysis were found in the available information.

- C. OPERATING RECORDS: The only operating features are the reservoir drain gates which are normally closed. Operating records are not maintained at the dam facility, but reportedly the slide gate is presently operational and is exercised annually.



- D. POST-CONSTRUCTION CHANGES: Preliminary design drawings dated 1963, suggest that repairs, including the installation of steel reinforcement, were made to the concrete surfaces of the spillway channel sidewalls and reservoir drain control structure (refer to Plate Nos. 1 through 4).

Additional improvements included the construction of grouted stone gutters along the spillway channel sidewalls, construction of a 10 ft. wide drainage ditch parallel to the downstream embankment toe, and restoration of the dam crest surface.

- E. SEISMIC STABILITY: The dam is located in Seismic Zone 1 (low seismic probability). No calculations or references of embankment stability were found. Based upon this low seismic probability and recommended criteria for the evaluation of the seismic stability of dams, the seismic stability of the embankment is presumed to be adequate under these earthquake conditions.

SECTION 7  
ASSESSMENT AND RECOMMENDATIONS

7.1 DAM ASSESSMENT

A. EVALUATION

1. Embankment: The cause and origin of the observed seepage zone could not be conclusively established by visual observation and review of construction drawings. It is therefore recommended the seep and adjoining wet zone be periodically monitored by the dam owner to note any change in condition. Embankment surface deficiencies presented in Section 3.2-A are surficial in scope and are not considered to represent significant hazard to the dam. However, remedial repairs are recommended. In general, dam embankment crest and slopes are adequately maintained, and appear in good condition at the present time.
2. Appurtenant Structures: In general, the spillway channel, stilling basin, and reservoir drain control structure are assessed in good condition at the present time. Remedial repair of spalling and cracking of concrete surfaces should be made as necessary.
3. Overtopping Potential: U. S. Army Corps of Engineers dam safety criteria recommends a PMF spillway design flood for "intermediate" size, "high" hazard dams. HEC-1 Dam Safety Version computer analyses indicate the spillway channel can pass approximately 34 percent PMF without overtopping the dam. Analysis indicates PMF inflow will cause a 6 ft. overtopping for an estimated flow duration of 13.5 hours.
4. Spillway Adequacy: As presented in Section 5, overtopping of the dam by 37 percent PMF inflow is reasonably expected to cause dam failure. HEC-1 Dam Safety Version computer analyses indicate downstream flood stages would be raised by between 4.1 to 6.3 ft. in the event of the assumed dam failure. This increase in flood stage level is considered to significantly increase the loss of life and potential downstream damage. Therefore, the discharge capacity of the spillway channel is considered to be seriously inadequate. The dam is accordingly categorized as "unsafe, non-emergency" based on guideline criteria.

B. ADEQUACY OF INFORMATION: The construction drawings available for this review were of sufficient detail to adequately conduct a Phase 1 study.

C. NECESSITY FOR FURTHER INVESTIGATION: The dam owner should initiate additional studies by a professional engineer experienced in the design of dams to more accurately ascertain spillway channel adequacy and the extent of improvements required to provide sufficient discharge capacity or erosion/breaching protection for the dam.

D. URGENCY: The following recommendations should be implemented as soon as possible.

7.2 RECOMMENDATIONS: The following recommendations are presented based on the data obtained:

A. DAM AND APPURTENANT STRUCTURES

1. Implement additional studies by a professional engineer experienced in the design of dams to more accurately ascertain spillway channel adequacy and the extent of improvements required to provide sufficient discharge capacity or erosion/breaching protection for the dam. Improvements found necessary by the recommended study should be implemented immediately.
2. Monitor seepage and adjoining wet zone located at downstream embankment toe. If increased flow quantity or evidence of erosion is observed, the Department of Environmental Resources, Dam Safety Division should be notified immediately, and necessary corrective repairs made.
3. Backfill, mulch, and seed slope erosion, animal burrows and shallow depression located on embankment slopes and crest.
4. Repair, when necessary, spalled and cracked concrete surfaces on spillway channel sidewalls and reservoir drain control structure.

B. OPERATION AND MAINTENANCE PROCEDURES

1. Develop a formal flood surveillance and warning plan. Plan to include, but not limited to, the following:
  - a) Surveillance: Around-the-clock surveillance of spillway channel discharge and overtopping of dam during periods of unusually heavy rainfall.
  - b) Warning System: Formal warning procedures to alert downstream residents in the event of expected high flood flows.
  - c) Evacuation Plans: Adequate emergency contingency plans to evacuate downstream residents in the event or threat of a dam failure.
2. Periodically observe seepage zone and adjoining wet zone located downstream of dam embankment.

APPENDIX A  
VISUAL OBSERVATIONS CHECK LIST AND FIELD SKETCH

Laurel Hill  
Name Dam Lake Dam County Somerset State Pennsylvania National ID # PA 267

Type of Dam Earthfill Hazard Category Class I - High Hazard

Date(s) Inspection 11/20/79 Weather Clear Temperature 50°

Inspection Review Date March 4, 1980

Pool Elevation at Time of Inspection 1938.5 Tailwater at Time of Inspection Normal M.S.L.

Inspection Personnel:

Ackenheil & Associates  
Bureau of State Parks  
Victor Prokop

Timothy Debes  
Rick Gabell  
James Hannan  
James Hainley  
Michael McCarthy  
John Schultz

Recorder Timothy Debes

EMBANKMENT

<u>VISUAL EXAMINATION OF</u>	<u>OBSERVATIONS</u>	<u>REMARKS OR RECOMMENDATIONS*</u>
SURFACE CRACKS	None observed. Embankment crest and slopes have a dense grass covering.	
UNUSUAL MOVEMENT OR CRACKING AT OR BEYOND THE TOE	None observed.	
SLOUGHING OR EROSION OF EMBANKMENT AND ABUTMENT SLOPES	Eroded footpath located 160 ft. south of right abutment on the upstream embankment slope.	
VERTICAL AND HORIZONTAL ALIGNMENT OF THE CREST	No significant vertical or horizontal misalignment observed.	
RIPRAP FAILURES	None observed.	

\*REFER TO REPORT SECTIONS 3 AND 7

EMBANKMENT

<u>VISUAL EXAMINATION OF</u>	<u>OBSERVATIONS</u>	<u>REMARKS OR RECOMMENDATIONS</u>
SETTLEMENT	Shallow depression located in front of reservoir drain control structure on dam crest.	
JUNCTION OF EMBANKMENT AND ABUTMENT, SPILLWAY AND DAM	Gravel access road located at upstream embankment-abutment junction. Surface slope erosion along upstream and downstream spillway-abutment junctions.	
ANY NOTICEABLE SEEPAGE	Seep and adjoining wet zone observed located 45 ft. downstream of dam. The seep had a clear discharge at an estimated flow rate of 8 gpm.	
STAFF GAGE AND RECORDER	None.	
DRAINS	A six (6) in. dia. tile drain pipe was installed in the downstream embankment toe filter extending 100 ft. north from the spillway-embankment junction.	

OUTLET WORKS

(Reservoir Drain)

<u>VISUAL EXAMINATION OF</u>	<u>OBSERVATIONS</u>	<u>REMARKS OR RECOMMENDATIONS</u>
CRACKING AND SPALLING OF CONCRETE SURFACES IN OUTLET CONDUIT	Minor spalling and cracking evident on concrete surfaces of reservoir drain control structure.	
INTAKE STRUCTURE	Submerged.	
OUTLET STRUCTURE	Rectangular concrete culvert opening, exiting the right downstream spillway side wall. Field measurements in- dicate an outlet opening of 4 x 5.5 ft.	
OUTLET CHANNEL	Outlet stream channel is cobble lined with vegetated banks. Channel observed free of debris and flow obstruction.	
EMERGENCY GATE	None.	



UNGATED SPILLWAY

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
CONCRETE WEIR	Ogee crested weir.	
APPROACH CHANNEL	Approach channel observed free of debris and flow obstructions.	
DISCHARGE CHANNEL	Fifty-two ft. long concrete stilling basin with concrete sidewalls and reinforced concrete apron.	
BRIDGE AND PIERS	None.	

GATED SPILLWAY (NOT APPLICABLE)

<u>VISUAL EXAMINATION OF</u>	<u>OBSERVATIONS</u>	<u>REMARKS OR RECOMMENDATIONS</u>
CONCRETE SILL	N/A	
APPROACH CHANNEL	N/A	
DISCHARGE CHANNEL	N/A	
BRIDGE AND PIERS	N/A	
GATES AND OPERATION EQUIPMENT	N/A	

INSTRUMENTATION


<u>VISUAL EXAMINATION OF</u>	<u>OBSERVATIONS</u>	<u>REMARKS OR RECOMMENDATIONS</u>
MONUMENTATION/SURVEYS		Department of Forest and Water boundary marker located on downstream embankment slope, approximately 100 ft. north of spillway-embankment junction.
OBSERVATION WELLS	None.	
WEIRS	None.	
PIEZOMETERS	None.	
OTHER	N/A	

RESERVOIR

<u>VISUAL EXAMINATION OF</u>	<u>OBSERVATIONS</u>	<u>REMARKS OR RECOMMENDATIONS</u>
<b>SLOPES</b>	Reservoir slopes are vegetated primarily by forest, appear stable, and have gentle to moderate inclinations. No evidence of landslides or significant shoreline erosion was observed.	
<b>SEDIMENTATION</b>	Sediment transported from beach areas into reservoir during heavy runoff. Reservoir and spillway discharge water observed clear.	

DOWNSTREAM CHANNEL

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
CONDITION (OBSTRUCTIONS, DEBRIS, ETC.)	None observed.	
SLOPES		Channel side slopes are vegetated with grass and woody shrubs and appear stable.
APPROXIMATE NO. OF HOMES AND POPULATION		Approximately thirty (30) inhabited structures are located within the estimated downstream flood plain between the dam site and Barronvale, Pennsylvania.



TE: MARCH 21, 1980		NATIONAL DAM INSPECTION PROGRAM	LAUREL HILL LAKE DAM FIELD SKETCH
SCALE: NONE			
DR: JLM	CK: TED	ACKENHEIL & ASSOCIATES CONSULTING ENGINEERS BALTIMORE, MD.	
DWG. NO. A-10			

ELEV. (FT.)

1970

CONCRETE GUTTER

SPILLWAY

CONCRETE GUTTER

1930

A

DAM CREST PR  
1"=50'

ELEV. (FT.)

1950

1940

1930



2.5

3

SECTION A-  
1"=10'

NOTE:

ASSUMED DATUM ELEV. 1938.5 ON TOP  
OF OGEE CREST

$$220 = 111$$

2

~~नाशा ना ना ना ना ना~~

A-A

DATE: MARCH 21, 1980	NATIONAL DAM INSPECTION PROGRAM	LAUREL HILL LAKE DAM
SCALE: AS SHOWN		
DR: JLM CK: JGS	ACKENHEIL & ASSOCIATES CONSULTING ENGINEERS BALTIMORE, MD.	
DWG. NO. A-11		



APPENDIX B

CHECK LIST  
ENGINEERING DATA  
DESIGN, CONSTRUCTION, OPERATION  
PHASE 1

CHECK LIST  
ENGINEERING DATA  
DESIGN, CONSTRUCTION, OPERATION  
PHASE 1

NAME OF DAM Laurel Hill Lake Dam  
ID # PA 267


ITEM	REMARKS
AS-BUILT DRAWINGS	No as-built drawings are available. Construction drawings were provided by the Pennsylvania Department of Environmental Resources, Dam Safety Division (see Plate Nos. 1-5).
REGIONAL VICINITY MAP	See Appendix E, Sections of four (4) U.S.G.S. 7.5 min. quadrangle maps showing dam site location.
CONSTRUCTION HISTORY	Construction drawing(s) prepared by the Branch of Recreational Planning and State Cooperation of the National Park Service (Department of the Interior) dated February 26, 1937. Construction of the dam was completed in 1940. Construction drawings for a rehabilitation project were prepared by the Pennsylvania Department of Forests and Waters in 1963. Construction of the rehabilitation project was completed in 1964.
TYPICAL SECTIONS OF DAM	See Plate No. 5 and Drawing No. A-11.
OUTLETS - PLAN DETAILS CONSTRAINTS DISCHARGE RATINGS	Reservoir drain and spillway channel - see Plate Nos. 1-5. Highway bridge located 3000 ft. downstream from dam. None available.
RAINFALL/RESERVOIR RECORDS	None available.

ITEM	REMARKS
DESIGN REPORTS	None available.
GEOLOGY REPORTS	None available.
DESIGN COMPUTATIONS HYDROLOGY & HYDRAULICS DAM STABILITY SEEPAGE STUDIES	None available.
MATERIALS INVESTIGATIONS BORING RECORDS LABORATORY FIELD	None available.
POST-CONSTRUCTION SURVEYS OF DAM	None available.
BORROW SOURCES	Unknown.

ITEM	REMARKS
MONITORING SYSTEMS	None.
MODIFICATIONS	The following modifications were proposed by preliminary design drawings in 1963: construction of grouted stone gutters along spillway channel sidewalls, installation of 100 ft. rock and gravel filter and toe drain, installation of steel reinforcing and concrete surface repair of spillway channel sidewalls and reservoir drain control structure, replacing the slide gate control mechanisms, and restoration of the dam crest surface.
HIGH POOL RECORDS	None reported.
POST CONSTRUCTION ENGINEERING STUDIES AND REPORTS	None reported.
PRIOR ACCIDENTS OR FAILURE OF DAM DESCRIPTION REPORTS	None reported.
MAINTENANCE OPERATION RECORDS	Inspections reportedly performed annually by park superintendent and biennially by the National Park Service. However, no reports were available.

ITEM	REMARKS
SPILLWAY PLAN	See Plate No. 1.
SECTIONS	See Plate Nos. 2, 3 and 5.
DETAILS	See Plate Nos. 2, 3 and 5.
OPERATING EQUIPMENT PLANS & DETAILS	See Plate Nos. 1, 2 and 4.
SPECIFICATIONS	None available.
MISCELLANEOUS	Assumed datum El. 1938.5 on top of ogee crest.

**APPENDIX C**  
**PHOTOGRAPHS**



DATE: MARCH 21, 1980

SCALE: NONE

DR: JLM CK: TED

DWG. NO. C-1

NATIONAL DAM INSPECTION PROGRAM

ACKENHEIL & ASSOCIATES  
CONSULTING ENGINEERS  
BALTIMORE, MD.

LAUREL HILL

LAKE DAM

SITE

PHOTOGRAPH 1

View of upstream embankment slope from right abutment.

PHOTOGRAPH 2

View of downstream embankment slope and spillway channel sidewall looking upstream.

PHOTOGRAPH 3

Overview of dam crest from spillway-embankment junction.

PHOTOGRAPH 4

Seepage toe drain outlet.





1



2



3



4

PHOTOGRAPH 5

View of spillway channel ogee crest and left sidewall. Note spalling and cracking on concrete surface.

PHOTOGRAPH 6

View of spillway channel and stilling basin looking upstream.

PHOTOGRAPH 7

Overview of reservoir and watershed.

PHOTOGRAPH 8

Downstream hazard at Station 1.



5



6



7



8

APPENDIX D

HYDROLOGIC AND HYDRAULIC  
ENGINEERING AND  
COMPUTER DATA

HYDROLOGIC AND HYDRAULIC  
ENGINEERING DATA

DRAINAGE AREA CHARACTERISTICS: Approximately 60% forest and 40% open  
pasture and cropland

ELEVATION TOP NORMAL POOL (STORAGE CAPACITY): 1938.5 ft. (395 ac.-ft.)

ELEVATION TOP FLOOD CONTROL POOL (STORAGE CAPACITY): 1950.0 ft. (1330 ac.-ft.)

ELEVATION MAXIMUM DESIGN POOL: 1950.0 ft.

ELEVATION TOP DAM: 1950.0 ft.

SPILLWAY CHANNEL

- a. Elevation Ogee crest at El. 1938.5
- b. Type Rectangular-shaped, concrete channel
- c. Width 115 ft. at Ogee crest
- d. Length 30.5 ft.
- e. Location Spillover Left (south) abutment
- f. Number and Type of Gates None

RESERVOIR DRAIN

- a. Type 4 x 4 ft. concrete culvert
- b. Location through and along right (north) spillway channel sidewall
- c. Entrance Inverts El. 1915.0
- d. Exit Inverts El. 1913.0
- e. Emergency Drawdown Facilities Manually-operated slide gate  
housed in concrete control structure at dam crest adjacent to  
right (north) spillway channel sidewall.

HYDROMETEOROLOGICAL GAGES

- a. Type None
- b. Location \_\_\_\_\_
- c. Records \_\_\_\_\_

MAXIMUM NON-DAMAGING DISCHARGE 16,600 cfs

HEC-1-DAM SAFETY VERSION  
HYDROLOGY AND HYDRAULIC ANALYSIS  
DATA BASE

NAME OF DAM:	Laurel Hill Lake Dam
Probable Maximum Precipitation (PMP)	24.0 in.*
Drainage Area	43.65 sq. mi.
Reduction of PMP Rainfall for Data Fit Reduce by 15.4% therefore PMP rainfall =	20.3 in.
Adjustments of PMF for Drainage Area	
6 hrs.	87%
12 hrs.	105%
24 hrs.	115%
48 hrs.	125%
Snyder Unit Hydrograph Parameters	
Zone	25**
C <sub>p</sub>	0.40
C <sub>t</sub>	1.0
L	12.4 mi.
L <sub>ca</sub>	6.12 mi.
t <sub>p</sub> = C <sub>t</sub> (L + L <sub>ca</sub> ) <sup>0.3</sup> =	3.66 hrs.
Loss Rates	
Initial Loss	1.0 in.
Constant Loss Rate	0.05 in./hr.
Base Flow Generation Parameters	
Flow at Start of Storm	1.5 cfs/sq. mi. = 65.5 cfs
Base Flow Cutoff	0.05 Q <sub>p</sub>
Recession Ratio	2.0
Spillway Channel Section	
Crest Length	115 ft.
Sidewall Height	12 ft.
Discharge Coefficient	3.7
Exponent	1.5
Discharge Capacity	16,600 cfs
Breach Parameters	
Section Width (Bottom)	70 ft.
Section Height	30 ft.
Duration of Failure	0.5 hrs.
Depth of Maximum Overtopping Prior to Failure	0.75 ft.

\*Hydrometeorological Report 33

\*\*Hydrological zone defined by Corps of Engineers, Baltimore District,  
for determining Snyder's Coefficients (C<sub>p</sub> and C<sub>t</sub>).

BY JGS  
 DATE 17 MAR 80  
 CHECKED TED  
 DATE 21 MAR 80

ACKENHEIL & ASSOCIATES  
 CONSULTING ENGINEERS  
 1500 N. MICHIGAN

PROJECT NO. 79067

SUBJECT: LAUREL HILL LAKE STORAGE VERSUS WSEL  
 LAUREL HILL LAKE DAM

SHEET NO. 1 OF 1

1) LAKE SURFACE AREAS DETERMINED BY PLANIMETER  
 OF CONTOURS OF 7½' USGS QUAD SHEETS  
 EXCEPT FOR WSEL = 1920', WHICH WAS ESTIMATED  
 FROM 15' QUAD SHEET.

2) USING CONIC SECTION METHOD,

$$\Delta V = \frac{h}{3} (A_1 + \sqrt{A_1 A_2} + A_2)$$

WHERE  $h = (WSEL)_2 - (WSEL)_1$

WSEL (ft.)	h (ft.)	AREA (ac.)	ΔV (AF)	V (AF)
1914.0		0		0
1920	6	0.5	1.0	1
1938.5	18.5	58	394	395
1960	21.5	107	1747	2141

\*\*\*\*\*  
 FLOOD HYDROGRAPH PACKAGE (HEC-1)  
 DAM SAFETY VERSION JULY 1978  
 LAST MODIFICATION 26 FEB 79  
 \*\*\*\*\*

1	A1	NON-BREACH ANALYSIS OF LAUREL HILL LAKE DAM									
2	A2	MIDDLECREEK TWP. SOMERSET CO., PA.									
3	A3	SNYDER UH., RATIOS OF PMF, & MOD PULS ROUTING									
4	B	300	0	30	0	0	0	0	0	0	-4
5	B1	5	0	0							
6	J	1	9	1							
7	J1	0.2	0.3	0.33	0.35	0.37	0.40	0.50	0.75	1.0	
8	K	0	LAKE								
9	K1	COMPUTATION OF INFLOW HYDROGRAPH TO LAUREL HILL LAKE									
10	M	1	1	43.65	0	0	0	1		1	
11	P	0	24.0	87	105	115	125				
12	T	0	0	0				1	0.05		
13	W	3.66	0.4	0							
14	X	-1.5	-0.05	2.0							
15	K	1	DAM								
16	K1	MOD PULS ROUTING OF FLOW THROUGH LAUREL HILL DAM									
17	Y	0	0	0	1	1					
18	Y1	1	0	0	0			395			
19	SS	0	1	395	2140						
20	SE	1914	1920	1938.5	1960						
21	SS1938.5	115	3.7	1.5							
22	SD	1950	3.1	1.5	46						
23	SL	46	170	335	430	470	550	620			
24	SV	1950	1950.5	1951.2	1952	1952.6	1955	1960			
25	K	99									

COMPUTER INPUT - OVERTOPPING ANALYSIS



**PLAN 1 .....**

## COMPUTER OUTPUT - SUMMARY OF OVERTOPPING ANALYSIS

\*\*\*\*\*  
FLOOD HYDROGRAPH PACKAGE (HEC-1)  
DAM SAFETY VERSION JULY 1978  
LAST MODIFICATION 26 FEB 79  
\*\*\*\*\*

```

1 A1 BREACH & NON-BREACH ANALYSIS OF LAUREL HILL LAKE DAM WITH DOWNSTREAM ROUTING
2 A2 MIDDLECREEK TWP. SOMERSET CO., PA.
3 A3 SNYDER UH., RATIOS OF PMF, & MOD PULS ROUTING
4 B 300 0 30 0 0 0 0 0 -4 0
5 B1 5 0 0
6 J 2 2 1
7 J1 0.37 0.5
8 K 0 LAKE 1
9 K1 COMPUTATION OF INFLOW HYDROGRAPH TO LAUREL HILL LAKE
10 M 1 1 43.65 0 0 0 1
11 P 0 24.0 87 105 115 125
12 T 0 0 0 1 0.05
13 W 3.66 0.4 0
14 X -1.5 -0.05 2.0
15 K 1 DAM 1
16 K1 MOD PULS ROUTING OF FLOW THROUGH LAUREL HILL DAM
17 Y 0 0 0 1 0
18 Y1 1 0 0 0 395
19 $S 0 1 395 2140
20 $E 1914 1920 1938.5 1960
21 $$1938.5 115 3.7 1.5
22 $D 1950 3.1 1.5 46
23 $L 46 170 335 430 470 550 620
24 $V 1950 1950.5 1951.2 1952 1952.6 1955 1960
25 Y 0 0 0 1 1
26 Y1 1 0 0 0 0 0 395
27 $S 0 1 395 2140
28 $E 1914 1920 1938.5 1960
29 $$1938.5 115 3.7 1.5
30 $D 1950 3.1 1.5 46
31 $L 46 170 335 430 470 550 620
32 $V 1950 1950.5 1951.2 1952 1952.6 1955 1960
33 $B 70 0.25 1920 0.5 1938.5 1950.75
34 K 1 STA 1 1
35 K1 MOD PULS ROUTING OF FLOW FROM DAM TO STA 1
36 Y 0 0 0 1 1
37 Y1 1
38 Y6 0.05 0.035 0.05 1908 1940 2900 0.01
39 Y7 0 1940 550 1921.5 600 1920 615 1908 700 1908.
40 Y7 715 1920 1565 1930 2165 1940
41 K 1 STA 2 1
42 K1 MOD PULS ROUTING OF FLOW FROM STA 1 TO STA 2
43 Y 0 1 1
44 Y1 1
45 Y6 0.05 0.035 0.05 1906 1940 2500 0.001
46 Y7 0 1940 200 1920 220 1918 235 1906 320 1906.
47 Y7 335 1918 350 1920 1450 1940

```

COMPUTER INPUT - BREACH CONDITION

48	K	1	STA 3					1			
49	K1		MOD PULS	ROUTING OF FLOW FROM STA 2 TO STA 3							
50	Y	0			1	1					
51	Y1	1									
52	Y6	0.05	0.035	0.05	1905	1940	1200	0.001			
53	Y7	0	1940	100	1930	140	1920	150	1905	250	1905.
54	Y7	265	1915	295	1920	1195	1940				
55	K	1	STA 4								
56	K1		MOD PULS	ROUTING OF FLOW FROM STA 3 TO STA 4							
57	Y	0			1	1					
58	Y1	1									
59	Y6	0.05	0.035	0.05	1902	1940	2900	0.001			
60	Y7	0	1940	70	1920	110	1914	125	1902	195	1902.
61	Y7	215	1920	365	1938	385	1940				
62	K	99									

COMPUTER INPUT - BREACH CONDITION

**PLAN 1 .....**

.....	ELEVATION STORAGE OUTFLOW	INITIAL VALUE 1938.50 395. 0.	SPILLWAY CREST 1938.50 395. 0.	TOP OF DAM 1950.00 1328. 16594.		
RATIO OF PMF	MAXIMUM RESERVOIR W.S.ELEV	MAXIMUM DEPTH OVER DAM	MAXIMUM STORAGE AC-FT	MAXIMUM OUTFLOW CFS	DURATION OVER TOP HOURS	TIME OF MAX OUTFLOW HOURS
.37	1950.77	.77	1391.	18531.	3.00	44.00
.50	1952.44	2.44	1526.	25164.	6.00	43.50
						0.00
						0.00

## PLAN 2 .....

.....	ELEVATION STORAGE OUTFLOW	INITIAL VALUE 1938.50 395. 0.	SPILLWAY CREST 1938.50 395. 0.	TOP OF DAM 1950.00 1328. 16594.	RATIO OF PMF	MAXIMUM RESERVOIR W.S.ELEV	MAXIMUM DEPTH OVER DAM	MAXIMUM STORAGE AC-FT	MAXIMUM OUTFLOW CFS	DURATION OVER TOP HOURS	TIME OF MAX OUTFLOW HOURS	TIME OF FAILURE HOURS
	1950.77	.77	1391.	38184.	1.70	44.50	44.00					
-.37	1951.14	1.14	1421.	42458.	.78	42.50	42.00					
-.50												

PLAN 1 STATION STA 1

RATIO	MAXIMUM FLOW,CFS	MAXIMUM STAGE, FT	TIME HOURS
.37	18539.	1918.5	44.00
.50	25144.	1920.4	43.50

PLAN 2 STATION STA 1

RATIO	MAXIMUM FLOW,CFS	MAXIMUM STAGE,FT	TIME HOURS
.37	35304.	1922.6	44.50
.50	39024.	1923.2	42.50

PLAN 1 STATION STA 2

RATIO	MAXIMUM FLOW,CFS	MAXIMUM STAGE,FT	TIME HOURS
.37	18528.	1924.7	44.00
.50	25183.	1927.0	44.00

PLAN 2 STATION STA 2

RATIO	MAXIMUM FLOW,CFS	MAXIMUM STAGE,FT	TIME HOURS
.37	31403.	1928.7	45.00
.50	36964.	1930.0	43.00

PLAN 1 STATION STA 3

RATIO	MAXIMUM FLOW,CFS	MAXIMUM STAGE,FT	TIME HOURS
.37	18499.	1923.2	44.00
.50	25190.	1925.8	44.00

COMPUTER OUTPUT - SUMMARY BREACH CONDITION

PLAN 2 STATION STA 3

RATIO	MAXIMUM FLOW,CFS	MAXIMUM STAGE,FT	TIME HOURS
.37	32323.	1928.1	45.00
.50	37658.	1929.5	43.00

PLAN 1 STATION STA 4

RATIO	MAXIMUM FLOW,CFS	MAXIMUM STAGE,FT	TIME HOURS
.37	18459.	1923.4	44.00
.50	25186.	1926.7	44.00

PLAN 2 STATION STA 4

RATIO	MAXIMUM FLOW,CFS	MAXIMUM STAGE,FT	TIME HOURS
.37	32360.	1929.7	45.00
.50	37320.	1931.5	43.00

The following table summarizes flood stages calculated by the computer model for 37 percent PMF runoff before and after dam failure:


<u>Damage Center</u>	<u>Maximum Flood Stage Before Failure</u>	<u>Maximum Flood Stage After Failure</u>	<u>Stage Increase (ft.)</u>
Sta. 1	1918.5	1922.6	4.1
Sta. 2	1924.7	1928.7	4.0
Sta. 3	1923.2	1928.1	4.9
Sta. 4	1923.4	1929.7	6.3

SUMMARY OF FLOOD STAGES FOR 37 PERCENT PMF

D-11

**APPENDIX E**  
**LOCATION PLAN AND PLATES**





DATE: MARCH 21, 1980

SCALE: 1:24000

DR: JLM CK: TED


DWG. NO. E-1

NATIONAL DAM INSPECTION PROGRAM

ACKENHEIL & ASSOCIATES  
CONSULTING ENGINEERS  
BALTIMORE, MD.

LOCATION PLAN  
OF LAUREL HILL  
LAKE DAM SITE

DWG. NO. R 56:2-1-1




CREST DETAIL  
Scale 4 in. = 1 ft.


DRAWING INDEX	
TITLE	DWG. NO.
GENERAL PLAN	1.1
RIGHT SPILLWAY WALL	1.2
LEFT SPILLWAY WALL	1.3
CONTROL STRUCTURE	1.4

GENERAL NOTES:


1. Location and dimensions of structures that are underground or underwater are believed to be reasonably correct but are not guaranteed to be absolutely so and are presented only as approximations.
2. For Concrete Notes, see Div. No. 1.2.
3. All elevations shown are based on Pennsylvania Department of Forests and Waters datum. Elevation of features are to be taken from bench marks shown on drawing.
4. Numbers shown in circle as (1) indicate number of payment item.
5. The Contractor shall, where directed, fill and grade in such a manner to provide drainage for areas adjacent to new construction.
6. Chain line fence 4'-0" high to be erected on top of right spillway wall for full length. See Div. No. 1.2.
7. The minimum width of access road at toe of embankment shall be 10 feet. To provide this width, a limited amount of regrading of the existing road may be necessary. See Special Requirement No. 6.
8. The final depth and limit of Removal of Concrete Structures shall be determined by the Engineer during construction of this project.
9. It may be necessary to remove and recompact loose fill along right spillway wall. The limits of such removal and recompaction will be determined by the Engineer in the field. Payment will be made at the applicable unit price for existing excavation and backfill.




GRAVITY STONE GUTTER  
Scale 4 in. = 1 ft.



TRAPEZOIDAL DITCH  
Scale 1/2 in. = 1 ft.



GRAVEL DRAIN  
Scale 1/2 in. = 1 ft.



MATERIAL	GRADATION REQUIREMENT
Rock Size	See Specs. for 12" drainage pipe p. 5-6
Gravel	See Specs. for 12" drainage pipe p. 5-6
Gravel Drain	See Specs. for Gravel Drain p. 10-2
Selected Material Surfacing	FD 8 Gradation 2A

THIS PAGE IS BEST QUALITY PRACTICABLE  
FROM COPY

DWG. NO.
11
12
13
14

underground of  
but are not  
and only as approximation  
Department of  
be are to be taken  
payment, too  
is in such a manner  
construction  
right way may  
Monument shall be  
grading of the  
Monument No. 6  
to Structures  
for during construction  
base for along right  
inspection will be  
will be made at  
and befall




LOCATION MAP  
Scale 1 in = 5 mi.

PROJECT

56-66A-1  
RECEIVED IN THE OFFICE OF THE WATER & POWER  
RESOURCES BOARD, DEPARTMENT OF FORESTS &  
WATER ON THE 2 DAY OF APRIL 1963  
Charles B. ...  
For Chief

REPORT NO. 87  
DATE 11/19/55

D.M. No. 4  
11/19/55



PRELIMINARY

COMMONWEALTH OF PENNSYLVANIA  
DEPARTMENT OF FORESTS AND WATERS  
DIVISION OF FLOOD CONTROL

LAUREL HILL STATE PARK DAM  
REHABILITATION PROJECT  
GENERAL PLAN

LAUREL HILL CREEK MIDDLECREEK TWP. PA.  
SOMERSET CO.



DESIGNED	DRAWN	CHECKED	DATE
RECORDED	REVIEWED	CHIEF FLOOD CONTROL DIV.	
		CHIEF ENGINEER	
		SECRETARY	

SECTION A-A  
No Scale




Existing downstream face of dam  
Existing dam crest  
Existing rock toe  
Excavation  
See Note 12

PLATE NO. 1 DWG. NO. R 56-2-1.1

DWG. NO. R56:2-12



ELEVATION  
(True projection of curved railway wall)  
Scale 1/4 inch = 1 foot



THIS PAGE IS BEST QUALITY PRACTICABLE  
FROM COPY FURNISHED TO DDC



The diagrams illustrate the construction of a bridge approach. The leftmost diagram, labeled 'SECTION A-A', shows a cross-section of a concrete structure with a 'Face of existing springing wall' at elevation 1937.8. It includes labels for 'Original ground', '1/2" Saw cut', 'Mass concrete removal', 'Chip concrete surface', 'Excavation and Compacted Backfill', and '1/2" Saw cut'. The middle diagram shows a cross-section of a bridge pier with a 'Grout Stone Sutter 12" Paving with 6" fiber blanket' on top. It includes labels for 'Original ground', 'Seeding', '3'-0" 3'-0"', '1/2" Saw cut', 'Mass concrete removal', 'Compacted Backfill', 'Subgrade paper', 'Excavation', '1/2" Saw cut', 'Grout Stone Sutter', '12" Paving with 6" fiber blanket', 'Chip concrete surface', and 'Open El. 1937.8'. The rightmost diagram shows a cross-section of a bridge pier with a 'Seeding' area and 'Original ground' line. It includes labels for 'Seeding', 'Original ground', 'Excavation See Sect. or B-B', and 'Compacted backfill'.

SECTION B-B  
(Typical Pavement Section)  
(Reinforcement detail not shown  
Scale 3/4" = 1'-0"

SECTION C-C  
Reinforcement steel not  
Scale 3/4" = 1'-0"





## SECTION E-E

SECTION F-6  
1" TYPE 304 OR 316 SS  
SEAM WELD

CETAL A  
5030 km. R

~~THIS PAGE IS BEST QUALITY PRACTICABLE~~  
~~FROM COPY FURNISHED TO DDC~~

56-66-4-3  
 RECEIVED IN THE OFFICE OF THE WATER & FOREST RESOURCES BOARD, DEPARTMENT OF FORESTS & WATERS ON THE 30th DAY OF April A.D. 1962  
Thurston  
 RECD. \_\_\_\_\_ FOR \_\_\_\_\_  
 SEE REPORT NO. 101  
W. H. H. H.  
W. H. H. H.



OUTLET HEADWALL  
 (See Drawing No. 1 for section)

**PRELIMINARY**

COMMONWEALTH OF PENNSYLVANIA  
 DEPARTMENT OF FORESTS AND WATERS  
 DIVISION OF FLOOD CONTROL

**LAUREL HILL STATE PARK DAM  
 REHABILITATION PROJECT  
 LEFT SPILLWAY WALL**

LAUREL HILL CREEK MIDDLECREEK TWP. PA.  
 SOMERSET CO

DESIGNED BY RECORDED APPROVED	DATE BY RECORDED APPROVED	DATE BY RECORDED APPROVED

DWG. NO. R56.2-1.3

PLATE NO.3

THIS PAGE IS BEST QUALITY PRACTICABLE  
 FROM COPY FURNISHED TO BDG

2



Scale 40 =




524 A. A. A.



5:12 1. 2. 3. 4. 5. 6. 7. 8. 9. 10. 11. 12. 13. 14. 15. 16. 17. 18. 19. 20. 21. 22. 23. 24. 25. 26. 27. 28. 29. 30. 31. 32. 33. 34. 35. 36. 37. 38. 39. 40. 41. 42. 43. 44. 45. 46. 47. 48. 49. 50. 51. 52. 53. 54. 55. 56. 57. 58. 59. 60. 61. 62. 63. 64. 65. 66. 67. 68. 69. 70. 71. 72. 73. 74. 75. 76. 77. 78. 79. 80. 81. 82. 83. 84. 85. 86. 87. 88. 89. 90. 91. 92. 93. 94. 95. 96. 97. 98. 99. 100. 101. 102. 103. 104. 105. 106. 107. 108. 109. 110. 111. 112. 113. 114. 115. 116. 117. 118. 119. 120. 121. 122. 123. 124. 125. 126. 127. 128. 129. 130. 131. 132. 133. 134. 135. 136. 137. 138. 139. 140. 141. 142. 143. 144. 145. 146. 147. 148. 149. 150. 151. 152. 153. 154. 155. 156. 157. 158. 159. 160. 161. 162. 163. 164. 165. 166. 167. 168. 169. 170. 171. 172. 173. 174. 175. 176. 177. 178. 179. 180. 181. 182. 183. 184. 185. 186. 187. 188. 189. 190. 191. 192. 193. 194. 195. 196. 197. 198. 199. 200. 201. 202. 203. 204. 205. 206. 207. 208. 209. 210. 211. 212. 213. 214. 215. 216. 217. 218. 219. 220. 221. 222. 223. 224. 225. 226. 227. 228. 229. 230. 231. 232. 233. 234. 235. 236. 237. 238. 239. 240. 241. 242. 243. 244. 245. 246. 247. 248. 249. 250. 251. 252. 253. 254. 255. 256. 257. 258. 259. 260. 261. 262. 263. 264. 265. 266. 267. 268. 269. 270. 271. 272. 273. 274. 275. 276. 277. 278. 279. 280. 281. 282. 283. 284. 285. 286. 287. 288. 289. 290. 291. 292. 293. 294. 295. 296. 297. 298. 299. 300. 301. 302. 303. 304. 305. 306. 307. 308. 309. 310. 311. 312. 313. 314. 315. 316. 317. 318. 319. 320. 321. 322. 323. 324. 325. 326. 327. 328. 329. 330. 331. 332. 333. 334. 335. 336. 337. 338. 339. 340. 341. 342. 343. 344. 345. 346. 347. 348. 349. 350. 351. 352. 353. 354. 355. 356. 357. 358. 359. 360. 361. 362. 363. 364. 365. 366. 367. 368. 369. 370. 371. 372. 373. 374. 375. 376. 377. 378. 379. 380. 381. 382. 383. 384. 385. 386. 387. 388. 389. 390. 391. 392. 393. 394. 395. 396. 397. 398. 399. 400. 401. 402. 403. 404. 405. 406. 407. 408. 409. 410. 411. 412. 413. 414. 415. 416. 417. 418. 419. 420. 421. 422. 423. 424. 425. 426. 427. 428. 429. 430. 431. 432. 433. 434. 435. 436. 437. 438. 439. 440. 441. 442. 443. 444. 445. 446. 447. 448. 449. 450. 451. 452. 453. 454. 455. 456. 457. 458. 459. 460. 461. 462. 463. 464. 465. 466. 467. 468. 469. 470. 471. 472. 473. 474. 475. 476. 477. 478. 479. 480. 481. 482. 483. 484. 485. 486. 487. 488. 489. 490. 491. 492. 493. 494. 495. 496. 497. 498. 499. 500. 501. 502. 503. 504. 505. 506. 507. 508. 509. 510. 511. 512. 513. 514. 515. 516. 517. 518. 519. 520. 521. 522. 523. 524. 525. 526. 527. 528. 529. 530. 531. 532. 533. 534. 535. 536. 537. 538. 539. 540. 541. 542. 543. 544. 545. 546. 547. 548. 549. 550. 551. 552. 553. 554. 555. 556. 557. 558. 559. 560. 561. 562. 563. 564. 565. 566. 567. 568. 569. 570. 571. 572. 573. 574. 575. 576. 577. 578. 579. 580. 581. 582. 583. 584. 585. 586. 587. 588. 589. 590. 591. 592. 593. 594. 595. 596. 597. 598. 599. 600. 601. 602. 603. 604. 605. 606. 607. 608. 609. 610. 611. 612. 613. 614. 615. 616. 617. 618. 619. 620. 621. 622. 623. 624. 625. 626. 627. 628. 629. 630. 631. 632. 633. 634. 635. 636. 637. 638. 639. 640. 641. 642. 643. 644. 645. 646. 647. 648. 649. 650. 651. 652. 653. 654. 655. 656. 657. 658. 659. 660. 661. 662. 663. 664. 665. 666. 667. 668. 669. 670. 671. 672. 673. 674. 675. 676. 677. 678. 679. 680. 681. 682. 683. 684. 685. 686. 687. 688. 689. 690. 691. 692. 693. 694. 695. 696. 697. 698. 699. 700. 701. 702. 703. 704. 705. 706. 707. 708. 709. 710. 711. 712. 713. 714. 715. 716. 717. 718. 719. 720. 721. 722. 723. 724. 725. 726. 727. 728. 729. 730. 731. 732. 733. 734. 735. 736. 737. 738. 739. 740. 741. 742. 743. 744. 745. 746. 747. 748. 749. 750. 751. 752. 753. 754. 755. 756. 757. 758. 759. 760. 761. 762. 763. 764. 765. 766. 767. 768. 769. 770. 771. 772. 773. 774. 775. 776. 777. 778. 779. 780. 781. 782. 783. 784. 785. 786. 787. 788. 789. 790. 791. 792. 793. 794. 795. 796. 797. 798. 799. 800. 801. 802. 803. 804. 805. 806. 807. 808. 809. 810. 811. 812. 813. 814. 815. 816. 817. 818. 819. 820. 821. 822. 823. 824. 825. 826. 827. 828. 829. 830. 831. 832. 833. 834. 835. 836. 837. 838. 839. 840.



Scale 1: 0 to 100



**SALES & MARK**



Scale: 1 in. = 100'



25.19 4 m 2.1 ft



Sc 10. 1000 1000 1000




100 200 300 400 500 600 700 800 900 1000



[View this page in French](#)
[View this page in Spanish](#)




2



Scoring: 1 = 1 pt.

THIS PAGE IS BEST QUALITY PRACTICABLE  
FROM COPY FURNISHED TO DDC





THIS PAGE IS BEST QUALITY PRACTICABLE  
FROM COPY FURNISHED TO EDC

PRELIMINARY

COMMONWEALTH OF PENNSYLVANIA DEPARTMENT OF FORESTS AND WATERS DIVISION OF FLOOD CONTROL			
LAUREL HILL STATE PARK DAM REHABILITATION PROJECT CONTROL STRUCTURE			
LAUREL HILL CREEK		MIDDLECREEK TWP. PA. SOMERSET CO.	
DESIGNED BY J. H.	DRAWN BY J. H.	CHIEF FLOOD CONTROL DIV.	DATE
RECON BY J. H.	APP BY J. H.	CHIEF ENGR.	
		SECRETARY	

DWG. NO. R 56-2-1.4

PLATE NO. 4

SECRET

THIS PAGE IS BEST QUALITY PRACTICABLE  
FROM COPY FURNISHED TO DDC



THIS PAGE IS BEST QUALITY PRACTICE  
FROM COPY FURNISHED TO FBI




PLATE NO. 5



APPENDIX F  
REGIONAL GEOLOGY

LAUREL HILL LAKE DAM  
NDI ID. NO. PA 267  
REGIONAL GEOLOGY

Laurel Hill Lake Dam is located approximately 3.5 miles north of New Lexington, Pennsylvania in the Allegheny Mountain section of the Appalachian Plateau Province. This section of the plateau contains flexures of moderate intensity having a dominant trend between north 30° east and north 35° east.

There is no evidence of faulting on the land surface in this area. However, considerable faulting occurs at depths over 3,000 ft. Based on the depth of the faults, these faults are not considered to present a significant hazard to the dam.

Laurel Hill Lake Dam is located approximately 0.35 miles west of the New Lexington Syncline axis. The strata underlying the dam constitutes the western flank of this syncline and dips gently to the southeast. The dam overlies the contact of the Glenshaw and Freeport Formations of the Conemaugh and Allegheny Groups, respectively. The Freeport Formation consists of alternating shale, sandstone, coal, and clay. The Freeport Formation also contains the mineable Upper and Lower Freeport coal seams. However, no mining activities have been recorded in the immediate area of the dam site.

The National Park Service design drawing (Plate No. 5) indicates the dam is underlain by sandy clay, shale, and sandstone.

---

References

Geology and Mineral Resources of Southern Somerset County, Pennsylvania,  
Norman L. Flint, Pennsylvania Geological Survey, 1965, County Report  
56A.

**ROCKWOOD & BAKERSVILLE QUADRANGLES, SOMERSET COUNTY PENNSYLVANIA**

**SCALE:** 0  1/2 MILE 1:24000

**CONTOUR INTERVAL 20FT. DATUM IS MEAN SEA LEVEL**

### ----- INFERRED GROUP CONTACTS

**NEW LEXINGTON SYNCLINE**

DATA OBTAINED FROM PENNSYLVANIA GEOLOGICAL SURVEY'S GEOLOGIC MAP OF SOMERSET COUNTY, 1968  
REVISED 1973

DATE: MARCH 21, 1980	NATIONAL DAM INSPECTION PROGRAM	SITE GEOLOGY OF LAUREL HILL LAKE DAM
SCALE: AS SHOWN		
DR: JLM    CK: GRG		
DWG. NO. F-2	ACKENHEIL & ASSOCIATES CONSULTING ENGINEERS BALTIMORE, MD.	